



ILLUSTRATION
SHOWS UNSANITARY
WATER MAIN
CONSTRUCTIONS
CONDITIONS
USING PRIOR ART
METHODS AND
EQUIPMENT.



FIG. 1



GUY WALTER


6419 3RD AVENUE

BRADENTON, FL 34208

941-745-2427

TRI VALVE FOR BACK FLOW PREVENTER ASSEMBLY

FIG. 1A



~~TRI VALVE~~


~~delete lines~~

~~delete words~~

add 16
#5

move information to margin


FIG. 2



TRI VALVE FOR BACK FLOW PREVENTER ASSEMBLY


GUY WALTER
 6419 3RD AVENUE
 BRADENTON, FL 34208
 941-745-2427


FIG. 2




TRI VALVE

add buds
add lines
delete words
move information to margin
add #15, 5, 6, 12, 3, 4, 1, 7, 18, 16, 1
delete lines







PRIOR ART

FIG. 5




FIG. 6